SILVER DISTANCE:

A flight that includes a leg of at least 50 Km.

1) Straight Distance: from release to a landing, can be a barograph only with no declaration of turning points.

RELEASE AD N.B. HT LOSS RULE.

NOT
TOO
HIGH 2) Straight distance, from release to a fix.

LEGOF AT LEAST JOKAN

WHO FOR GET HOME

3) Declare 1 TP at least 50 Km from the start point, as in an out and return.

LEG OF AT LEAST SOKM DECLARED T.P.

4) Declare 2 or more TPs, such that there is a leg of at least 50 Km.

DECLARATION.